

**BRIDGE NO. A-02-023 (MARTIN STREET OVER FORT POND BROOK)****Bridge Description and Orientation:**

The Martin Street Bridge over Fort Pond Brook is a twin corrugated steel pipe arch culvert that was built in 1965 (see Sketches and Photos #1, #2 & #3). Martin Street, at the bridge, is oriented North and South over the Fort Pond Brook which flows West to East. The pipe arches are labeled South and North.

Summary of Existing Conditions:**Bridge Rail & Approach Guardrail Deficiencies (NBIS Item #36 in Inspection Report)**

Element	Deficiency	Reference Photo(s)
Bridge Rail / Approach Guardrail	<ul style="list-style-type: none">No deficiencies noted	3

Top of Bridge Deficiencies (NBIS Item #58 in Inspection Report)

Element	Deficiency	Reference Photo(s)
Wearing Surface	<ul style="list-style-type: none">Light to moderate vegetation growth at all 4 approaches to the bridge	3

Superstructure Deficiencies (NBIS Item #59 in Inspection Report)

Element	Deficiency	Reference Photo(s)
Corrugated Steel Pipe Arch Culvert	<ul style="list-style-type: none">Random missing connection bolts and minor deterioration of the protective coating with the majority of the protective coating failing along the waterlineMinor accumulation of debris along the bottom of both pipe archesModerate aggradation at the West end of both pipe archesEast end of North and South pipe arches are undermined up to 8"West end of North and South pipe arches are undermined up to 12"	2
	<ul style="list-style-type: none">Moderate to severe rusting with minor steel delamination along the lower haunch of both pipe arches, located approximately 12" above the bottom of barrel, just below the seam of the arch sections	4, 5, 6



	<ul style="list-style-type: none"> Hole in South pipe arch (North face), located 8'-7" from East end, that measures 2"L x 5"H x up to 4" of penetration Hole in South pipe arch (South face), located 12'-0" from East end, that measures 1" in diameter x up to 1.5" of penetration Hole in South pipe arch (South face), located 13'-6" from East end, that measures 2.5"L x 1.5"H x up to 2.5" of penetration Hole in South pipe arch (South face), located 21'-8" from East end, that measures 2"L x 2.5"H x up to 1" of penetration Hole in South pipe arch (South face), located 33'-8" from East end, that measures 3.5"L x 3"H x up to 3" of penetration 3 holes in South pipe arch (South face), located 36'-8" from East end, that measure 3"L x 3"H x up to 3" of penetration, 4"L x 5"H x up to 3.5" of penetration and 3"L x 5"H x up to 4" of penetration Hole in North pipe arch (North face), located 16'-0" from East end, that measures 1"L x 2"H x up to 1" of penetration Hole in North pipe arch (North face), located 18'-6" from East end, that measures 3"L x 3"H x up to 1" of penetration Hole in North pipe arch (North face), located 27'-0" from East end, that measures 2"L x 2"H x up to 3" of penetration Hole in North pipe arch (North face), located 40'-0" from East end, that measures 4"L x 5"H x up to 2" of penetration Hole in North pipe arch (North face), located 41'-6" from East end, that measures 4"L x 2.5"H x up to 3" of penetration Hole in North pipe arch (North face), located 42'-0" from East end, that measures 2"L x 1"H x up to 2" of penetration 	7 8 9 10 10 10
West Headwall	<ul style="list-style-type: none"> Light to heavy vegetation growth Random narrow to medium cracks in mortar, minor settlement of the stone throughout and minor erosion at the South side of the South pipe arch Void in 2nd row from channel bottom between pipe arches that measures full width x 6"H x up to 19" of penetration Void between South face of North pipe arch and West headwall that measures 16"H x 2"W x up to 26" of penetration 	11 1 1
East Headwall	<ul style="list-style-type: none"> Wide crack in mortar over South pipe arch Void at the North face of the South pipe arch and the headwall that measures 11"H x 8"W x up to 1" of penetration 	2



	• Void at bottom of headwall between pipe arches that measures 8.5"L x 3"W x up to 12" of penetration	2
	• Void at South face of North pipe and headwall that measures 9"H x 6"W x up to 4'-9" of penetration	2


Abutment/Foundation Deficiencies (NBIS Item #60 in Inspection Report)

Element	Deficiency	Reference Photo(s)
Wingwalls	• Light to moderate vegetation growth throughout all 4 wingwalls	

Recommended Maintenance:

The following table outlines the deficiencies and repairs needed, along with the priority of the repair, to the Martin Street Bridge over Fort Pond Brook:


Element & Location		Deficiency	Repair Needed	Priority
#1	Protective coating of pipe arches	Cracking and peeling throughout	Clean and reseal with protective coating throughout	High
#2	East end, both pipe arches	Undermining up to 8"	Place riprap at ends and seal voids around pipe arches	High
#3	West end, both pipe arches	Undermining up to 12"	Place riprap at ends and seal voids around pipe arches	High
#4	Haunch of both pipe arches	Moderate to severe rusting	Pave inverts full length within normal water range	High
#5	South pipe arch, South face	Numerous holes in arch at haunch	Repair holes prior to placing new paved invert	High
#6	South pipe arch, North face	Hole in arch at haunch	Repair holes prior to placing new paved invert	High
#7	North pipe arch, North face	Numerous holes in arch at haunch	Repair holes prior to placing new paved invert	High
#8	Stone masonry headwalls	Narrow to medium cracks in mortar	Repoint stone masonry headwalls as needed	Low
#9	Pipe arch / headwall ends	Voids around pipe arches and undermining of pipe arches	Fill voids with concrete to seal gaps	High



ACTION: MARTIN STREET OVER
FORT POND BROOK, BRIDGE NO. A-02-023
PLAN - SCALE: N.T.S.

CHAS. H. SELLS, INC.
 Consulting Engineers, Surveyors & Planners






**ACTION: MARTIN STREET OVER
FORT POND BROOK, BRIDGE NO. A-02-023
BRIDGE TRANSVERSE SECTION - SCALE: N.T.S.**

CHAS. H. SELLS, INC.
Professional Engineers, Surveyors & Photogrammetrists





LEGEND
 — - CONTOUR
 ☒ - SEPARATION BENCH

STAGE I

**ACTION: MARTIN STREET OVER
 FORT POND BROOK, BRIDGE NO. A-02-023
 WATER CONTROL PLAN - SCALE: N.T.S.**





CHAS. H. SELLS, INC.



ACTION: MARTIN STREET OVER
FORT POND BROOK, BRIDGE NO. A-02-023
WATER CONTROL PLAN - SCALE: N.T.S.



Bridge #: A-02-023

Photo #: 1

09/19/2007

West Elevation View, looking West.



Bridge #: A-02-023

Photo #: 2

09/19/2007

East Elevation View, looking Southwest.



Bridge #: A-02-023

Photo #: 3

View of South approach roadway looking North across bridge.



Bridge #: A-02-023

Photo #: 4

(Moderate to severe rusting)

09/19/2007

View of South face of South pipe arch (near the East end) showing heavy to severe rusting, looking Southwest.

Bridge #: A-02-023

Photo #: 5

(Moderate to severe rusting)

09/19/2007

View of South face of South pipe arch (near the midspan) showing heavy to severe rusting, looking Southwest.


Bridge #: A-02-023

Photo #: 6

(Moderate to severe rusting)

09/19/2007

View of South face of North pipe arch showing heavy to severe rusting, looking Southwest.




Bridge #: A-02-023

Photo #: 7

3.5" long x 3" high x up to 3" penetration

09/19/2007

View of South face of South pipe arch, approximately 33'-8" from the East end.



Bridge #: A-02-023

Photo #: 8

3.5" long x 3" high x up to 3" penetration

3" long x 3" high x 3" penetration

4" long x 5" high x 3.5" penetration

3" long x 5" high x 4" penetration

09/19/2007

View of South face of South Barrel, approximately 36'-8" from the East end.



Bridge #: A-02-023

Photo #: 9

09/19/2007

1" long x 2" high x up to 1" penetration

3" long x 3" high x up to 1" penetration

View of North face of North Barrel, approximately 17'-0" from the East end.



Bridge #: A-02-023

Photo #: 10

2" long x 1" high x
up to 2" penetration

2" long x 2" high
x up to 3" deep

4" long x 2.5" high x
up to 3" penetration

09/19/2007

View of North face of North Barrel, approximately 42'-0" from the East end.

Bridge #: A-02-023

Photo #: 11

09/19/2007

View of Southwest corner of the bridge showing heavy vegetation growth, looking East.

